

TITLE V, FEDERAL SURPLUS PROPERTY PROGRAM
REPORT FOR 04/21/2023

Title V Eligible Organizations

Eligible organization means a State, unit of local government or a private non-profit organization which provides assistance to the homeless, and which is authorized by its charter or by State law to enter into an agreement with the Federal government for use of real property for the purposes of this subpart (24 CFR Part 581). Representatives of the homeless interested in receiving a deed for a particular piece of surplus Federal property must be section 501(c)(3) tax exempt.

UNSUITABLE PROPERTIES / BUILDING
SOUTH DAKOTA

Pactola Range Storage #2

23060 Custer Gulch Road

Rapid City SD 57702

Landholding Agency: USDA-FS

Property Number: 13202320019

Status: Unutilized

Directions: CN 47924010421

Comments: Offsite Removal. 37-year-old; 51 SF woof storage building. Structurally unsound; in disrepair. Possible contamination due to small mammal/rodent nesting materials, urine, and feces.

Reasons:

- Structural Damage - Extensive Deterioration

WYOMING

Doyle Campground Toilet

See directions.

Buffalo WY

Landholding Agency: USDA-FS

Property Number: 13202320014

Status: Excess

Directions: Doyle Campground Toilet – RPU ID #4100.001041. From PRRD in Buffalo, WY, Take Hwy 16 west approximately 26 miles, then turn left onto Hazelton Rd. (county Rd. 3) continue on Hazelton Rd. for approximately 6 miles, turn left at the entrance to Doyle Campground(signed). Follow the loop around to Site #9 and toilet will be to the left.

Comments: Offsite Removal. 35-year-old, 64 SF toilet. Structurally unsound. In disrepair.

Reasons:

- Structural Damage - Extensive Deterioration

UNSUITABLE PROPERTIES / BUILDING
WYOMING

Elgin Park Trailhead Toilet

See directions.

Buffalo WY

Landholding Agency: USDA-FS

Property Number: 13202320015

Status: Excess

Directions: Elgin Park Trailhead Toilet - RPU ID #4242.001041. From PRRD in Buffalo, WY, take Hwy 16 west approximately 18 miles and turn left on Forest Road 22.

Approximately 1 mile turn right on Forest Road 460 approximately 3/4 of a mile, come to a Y and go left on Forest Road 372(signed for Elgin Park Trailhead) Approximately 1 mile you will turn left into Elgin Park Trailhead. Toilet will be near the entrance on the left.

Comments: Offsite Removal. 48-year-old; 72 SF toilet. Structurally unsound; in disrepair.

Reasons:

- Structural Damage - Extensive Deterioration

Hettinger Group Area Toilet

See directions.

Buffalo WY

Landholding Agency: USDA-FS

Property Number: 13202320016

Status: Excess

Directions: Hettinger Group Area Toilet – RPU ID #14156010452. From PRRD in Buffalo, WY, take Hwy 16 west approximately 13 miles and turn right on Forest Road 374 (signed as Hettinger Picnic Area) drive to the end of road approximately 1/2 mile and toilet will be on the north side of parking area.

Comments: Offsite Removal. 53-year-old; 124 SF toilet. Structurally unsound; in disrepair.

Reasons:

- Structural Damage - Extensive Deterioration

Lost Cabin Campground Toilet

See directions.

Buffalo WY

Landholding Agency: USDA-FS

Property Number: 13202320017

Status: Excess

Directions: Powder River Ranger District - Lost Cabin Campground Toilet – RPU ID #3998.001041. From PRRD in Buffalo, WY, Take Hwy 16 west approximately 27 miles, then turn right into Lost Cabin Campground (Signed) Follow loop around to just past Site# 14. Toilet will be on the right (North).

Comments: Offsite Removal. 53-year-old; 80 SF toilet. Structurally unsound; in disrepair.

Reasons:

- Structural Damage - Extensive Deterioration

North Fork Picnic Area Toilet

See directions.

Buffalo WY

Landholding Agency: USDA-FS

Property Number: 13202320018

Status: Excess

Directions: Powder River Ranger District - North Fork Picnic Area Toilet – RPU ID # 4227.001041. From PRRD in Buffalo, WY, take Hwy 16 west approximately 11 miles and turn right on Forest Road 19. Proceed approximately 1/4 mile to the picnic sight and the toilet is on the south side of Forest Road 19.

Comments: Offsite Removal. 53-year-old; 56 SF toilet. Structurally unsound; in disrepair.

Reasons:

- Structural Damage - Extensive Deterioration

Sitting Bull Campground

See directions.

Buffalo WY

Landholding Agency: USDA-FS

Property Number: 13202320020

Status: Excess

Directions: Powder River Ranger District - Sitting Bull Campground Toilet – RPU ID # 4075.001041. From PRRD in Buffalo, WY, Take Hwy 16 west approximately 43 miles, then turn right onto Forest Road 432 (signed Sitting Bull Campground). Proceed approximately 3/4 mile to Sitting Bull Campground. The toilet will be just past Site# 4 on the right (North).

Comments: Offsite Removal. 29-year-old; 90 SF toilet. Structurally unsound; in disrepair.

Reasons:

- Structural Damage - Extensive Deterioration

UNSUITABLE PROPERTIES / LAND
INDIANA

Cannelton Lock and Dam Site 44

County Road 111

Leavenworth IN 47137

Landholding Agency: GSA

Property Number: 54202320003

Status: Excess

GSA Number: 1-D-IN-606-AA

Directions: See address.

Comments: 27.48 acres of improved land (Power house, oil house, warehouse/garage, tool house, boat ramp, paved parking area, and access road). Located within a 100-year floodplain and in a floodway.

Reasons:

- Floodway